

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:								
Company	Kit Pappas Manager of Environmental/Engineering							
OGM	Karl Houskeeper Environmental Scientist III							

Inspection Report

Permit Number:	C0070020
Inspection Type:	COMPLETE
Inspection Date:	Thursday, January 15, 2009
Start Date/Time:	1/15/2009 9:30:00 AM
End Date/Time:	1/15/2009 12:00:00 PM
Last Inspection:	Thursday, December 11, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear/Sunny, Temp. 23 Deg. F.</u> InspectionID Report Number: <u>1887</u>

Accepted by: jhelfric

2/23/2009

Permitee: HIDDEN SPLENDOR RESOURCES INC Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

1,577.00	Total Permitted	✓ Federal	V	Underground
9.50	Total Disturbed	☐ State		Surface
	Phase I	☐ County		Loadout
	Phase II	✓ Fee		Processing
	Phase III	☐ Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

Inspector's Signature:

Harl R. Houskupen

Date

Thursday, January 15, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070020 Inspection Type: COMPLETE

Inspection Date: Thursday, January 15, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	V		\checkmark	
2.	Signs and Markers	✓		V	
3.	Topsoil	V			
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		Y	
4.c	Hydrologic Balance: Other Sediment Control Measures	Y			
4.d	Hydrologic Balance: Water Monitoring	V			
4.e	Hydrologic Balance: Effluent Limitations	V		¥	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	V		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	V			
15.	Cessation of Operations	V			
16.	a Roads: Construction, Maintenance, Surfacing	~			
16.	D Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	✓		V	
21.	Bonding and Insurance	V		V	
22.	Other	✓			

Permit Number: C0070020 inspection Type: COMPLETE

Inspection Date: Thursday, January 15, 2009

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/020 was issued effective 10/11/2006 and expires 10/11/2011.

- -Certificate of Insurance policy number 5591885, issued 10/03/2008 and terminates 10/03/2009
- -UPDES permit UTG040000 (General) UTG040019 (Site Specific) effective 05/01/2008 and expires midnight 04/30/2013.
- -Air Quality permit DAQE-700-70, issued November 7, 2000.
- -SPCC Plan dated June 2006. The Plan is P.E. certified, stamped, signed and dated 6/20/06 by a Utah P.E.

2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number.

4.a Hydrologic Balance: Diversions

Snow has been pushed into the diversion that runs adjacent to the office/bathhouse. Arrangements were made with surface personnel during the inspection to open the diversion up so that it could function as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The 2007 Annual pond inspection was done on 09/17/2007. First Quarter 2008 pond inspection was done on 02/13/08. Second Quarter 2008 pond inspection was done on 06/30/2008. Third Quarter pond inspection was done on 09/29/08. The estimated sediment elevation on the 3rd quarter pond inspection is at 7567.2 and the 60% sediment clean elevation is 7566.2 indicating that it is time to clean the pond. Fourth quarter 2008 elevations were noted the same as third quarter 2008. An additional note was included acknowledging the elevations and indicating that the pond will be cleaned in the spring of 2009. No other problems were noted

4.e Hydrologic Balance: Effluent Limitations

November and December 2008 discharge monitoring reports were reviewed. No parameters were exceeded.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-700-00 was issued on November 7, 2000. Recent documentation shows the approval order number as DAQP-002-06.

Inspection Continuation Sheet

Permit Number: C0070020 Inspection Type: COMPLETE

Inspection Date: Thursday, January 15, 2009

Page 4 of 4

21. Bonding and Insurance

The bond is secured by a letter of credit through Bank One in the amount of \$57,000 and collateral to add up to the amount of \$342,000. This letter of credit expired on January 20, 2007. The appraisal was updated as of 12/20/06 for the real estate (collateral) and the appraisal is now \$625,000 and the collateral is adequate. The updated reclamation cost estimate is \$445,000 in 2011 dollars.